

FIG.2




FIG.3


553

FIG.4




FIG.5

700

SCREEN

PRINT PROCESSING TIME ANALYSIS RESULT

?

X

CURRENT PRINT PROCESSING TIME DATA

PRINTER NAME : XXX PM—xxx
OUTPUT PORT : XXX. XXX (LPR PORT)
FILE NAME : XXX
STATUS : PRINTING

1) PRINTER MAXIMUM PROCESSING TIME : 370kbyte/sec
2) PRINTER CURRENT PROCESSING TIME : 100kbyte/sec
3) OUTPUT PORT DATA TRANSFER RATE : 100kbyte/sec
4) PRINTER DRIVER DATA GENERATION : 340kbyte/sec
PROCESSING TIME

PRINT PROCESSING TIME ANALYSIS RESULT

" DUE TO A LOW DATA TRANSFER RATE, DATA PROCESSING TIME
OF THE PRINTER AND DATA GENERATING ABILITY OF THE COMPUTER
ARE NOT EFFICIENTLY USED.
THE CURRENTLY USED PORT IS XXX.XXX (LPR PORT), AND BY
REPLACING WITH XXX/XX PORT, THE PRINT PROCESSING TIME
CAN BE IMPROVED.

CLOSE